IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re patent of:

Pettigrew et al.

Patent. No.: 7,031,812 B1

Issued: April 18, 2006

For: System and Method for Monitoring Aircraft Engine Health and Determining Engine

Power Available, and Applications Thereof

Confirmation No.: 9990

Art Unit: 3661

Examiner: Zanelli, M.

Atty. Docket: 2251.0010000

Request for Certificate of Correction Under 37 C.F.R. § 1.323 For Applicants' Mistake

Attn: Certificate of Correction Branch

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

It is hereby requested that a Certificate of Correction under 37 C.F.R. § 1.323 be issued for the above-captioned United States Patent. This Certificate of Correction is being requested due to a mistake which appears in the printed patent. The mistake made by Applicants is of a clerical or typographical nature, or of a minor character. Patentees submit that correction of this error does not introduce new matter.

Specifically, the printed patent contains the following error for which a Certificate of Correction is respectfully requested:

In column 14, line 1, "comprising:" should be replaced with -- comprises --.

Remarks

The above-noted correction does not involve such changes in the patent as would constitute new matter or would require reexamination.

A completed Form PTO/SB/44 accompanies this request, with the above-noted correction printed thereon. Accordingly, a Certificate of Correction is believed proper and issuance thereof is respectfully requested.

This request is accompanied by payment of the fee set forth in 37 C.F.R. § 1.20(a). Fee payment is provided through online credit card payment. The Commissioner is hereby authorized to charge any fee deficiency, or credit any overpayment, to our Deposit Account No. 19-0036.

Respectfully submitted,

STERNE, KESSLER, GOLDSTEIN & FOX P.L.L.C.

Virgil L. Beaston

Attorney for Patentees Registration No. 47,415

Date

1100 New York Avenue, N.W. Washington, D.C. 20005-3934

(202) 371-2600

560717_1.DOC

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page <u>1</u> of <u>1</u>

PATENT NO: 7,031,812 B1

DATED:

April 18, 2006

INVENTOR(S): Pettigrew et al.

It is certified that error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below.

In column 14, line 1, "comprising:" is replaced by -- comprises --.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

1100 New York Avenue, NW Washington DC 20005-3934 Atty. Dkt. No. 2251.0010000

This collection of information is required by 37 CFR 1.322, 1.323 and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you are required to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. **SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.**